

FSK/CW INTERFACE BOARD SERVICE BULLETIN 2
FT-1000MP SERIES TRANSCEIVERS – PTT OPERATION

Note: This Service Bulletin supersedes and replaces Service Bulletin 1.

Applicability:

Boards and interfaces for the FT-1000MP series transceivers shipped prior to 2/9/2010. If you have a board or interface purchased for a FT-1000MP series transceiver after that date, it is fully compatible with the FT-1000MP series and no modifications are required.

Problem:

Some FT-1000MP and FT-1000MP MKV users have experienced problems with PTT keying.

Recommended Action:

If you have a board or interface purchased before 2/9/2010, an upgrade is available to ensure proper keying of the PTT circuit. The upgrade consists of a new optical-isolator in the PTT circuit. You may take advantage of this upgrade even if you are not experiencing any PTT keying problems. For information on this upgrade please contact me at w3yy@cox.net.

73, Bob – W3YY